	er ID 71970 14, 2011 3:11:01										Page 1	
Item ID: Revision ID:	D3531-041		1	Accept					Setup			
Item Name:	Bracket Assembly									Stop		
Start Date: Required Date:		eq'd Qty: 5.00			Cust Item : Customer:							
Reference:												•
Approvals:	Process Plan:		Date: //-07-/4	Tooling:	D	ate:	· 		Run	Start Stop		
	QC:		Date:	<b>SPC</b> (Y/N):	D	ate:				эгор		
Sequence ID/ Work Center II		peration escription		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revisio	n Nbr										
D3531	Rev A											
	Sm	nall Fab		0.00				4	5,,	/18	/23	
Small Fab		Memo		0.00				<del></del>	<i>-                                    </i>	<i>v</i> -0 <sub>/</sub>	100	
Small Fab		Assemble a	s per dwg D3531						•			
110	00		oleteness to step on W/O	0.00								PI
	Ų	23- mspect part comp	inciences to step on w/O	$\sim$	. 1-				>			
QC .		Memo		0.00	worl23			(2)	<b>?</b>	<del></del>		
Quality Control												

120

Black Sandtex(Ref:4.3.5.7) per QSI005 4.3

0.00

Powdercoat

W 1,3728

Memo
START TIME:

3200

6X Ø m/24/01/25

W/O: 7/	976		V	VORK ORDER CHANGES					
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				<del></del>					
					,			,,,	
_	D35	31-041 PAR #: NA	Fault Ca	tegory: Sm. Fab N	ICR: Yes	No DQ	A: //	Date: _	1.08.29
17/1/	,, R	esolution: SCLAP						Date: _	11 08 29
NCR:		<b>W</b> (	ORK OR	DER NON-CONFORMANO	CE (NCI	3) S	67		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section B  Action Description Chief Eng	Sign Date	Verifi	<b>cation</b> ion C	Approval Chief Eng	Approval QC Inspector
			<del>  /)</del> -						
11/08/23	130	Unet was wacht when removed hate	OFFUR	Scrip - distoy	10/98/	1 2 11:00	· 23	De green	4.08.29
11(03/23		I post is scrap I when removed hate come singer	Ostup	Scrip = distoy	2/5 11/58/p	1 1100	r 23	Bosen	W-08:29
14/08/23		<u> </u>	Ostup	Scrip - distoy	2/5 11/98/	1 200	r 23	Boson	W-08:29
11/03/323		<u> </u>	Ortup	Scrip - distoy	2/5 11/98/	1 2 1100	r 23	Boson	W.08:29
11/03/23		<u> </u>	OFFUR	Scrip a distory	est port	1 200	r 23	Bosen	W.08.23
11/03/23		CProcess See	Ostup	Scrip = distory	2/5 11/98/	1 200	r 23	Bon	W.08:23

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

### Work Order ID 71976

Thursday, July 14, 2011 3:11:01 PM



Page 2

Item ID:

D3531-041

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Bracket Assembly ·

**Start Date:** 

7/14/2011

Start Oty: 5.00

Required Date: 7/22/2011

Req'd Qty: 5.00



Date:

**Cust Item ID: Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Date:

Run Start

Stop



Sequence ID/ **Work Center ID** 

130

Quality Control

Operation Description

OC3- Inspect Part Finish

Memo

Set Up/ **Run Hours** 

0.00

SPC (Y/N):

0.00

**Tool ID** 

Tool # Plan Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

140

Packaging

Packaging

Identify as per dwg & Stock Location

Memo

0.00

0.00

150

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Dai t Aci	ospace	Liu								
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,							
Part No	:	PAR #:	Fault Ca	tegory:	NCI	R: Yes N	10 <b>DQ</b>	A:	Date:	
	R	esolution:	_ Dispositi	ion:	QA	: N/C Clo	sed:		Date: _	
NCR:		W	ORK ORI	DER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	ction B	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector
								•		
						·				

## **Picklist Print**

Thursday, July 14, 2011 3:11:08 PM

Work Order ID: 71976

Parent Item:

D3531-041

Parent Item Name:

Bracket Assembly



Start Date: 7/14/2011

Required Date: 7/22/2011

Page 1

Start Qty: 5.00

Required Qty: 5.00

_						
	n	m	m	eπ	te.	•

IPP Rev:A New Issue 07-09-24 EC verified DD


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
03531-1 		Manufactured	No			<sup>100</sup> 3 7,	Each 1977	0.0000		Bu	/08/z	23	
D3531-3  Bracket Front Plate		Manufactured	No			B 7	Each / 7 7 8	0.0000 <b>7</b>		Zi,	/08/	23	
MS20470AD4-4 		Purchased	No			100	Each	1,160.000		18 1	1/08	/23	
				Location		Loc (	<u>Otv</u>	Loc Code					
				ST139			618				_		
					117423		618						
				ST319			542		_		_		
	•			•	116188		476				_		
		•			116391		66		_		_		

M118614 (84x)

Dan Aci	Ospace	Liu							
W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			ı						
							<u>.</u>		
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No <b>DQ</b>	A:	_ Date: _	
	R	esolution:	Dispositi	on:	QA: N/C CI	osed:		Date: _	
NCR:		\	WORK ORE	DER NON-CONFORMA	NCE (NCF	3)			
DATE	STEP	Description of NC	Initial	Corrective Action Section	on B Sign 8		cation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Date	Sect	ion C	Chief Eng	QC inspector
								!	
								:	



DESIGN	3	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAI	
CHECK	ED	APPROVED	D3531	REV. A SHEET 1 OF 3
DATE	07.0	06.19	BRACKET ASSEMBLY	SCALE 1:2
REV		DATE	DESCRIPTION	



## D3531-041 BRACKET ASSEMBLY

NOTES:
1) FINISH: POWDER COAT ASSEMBLY BLACK SANDTEX (4.3.5.7) PER DART QSI 005 4.3

ALL PARTŜ

2) ASSEMBLE PER DART QSI 003

3) IDENTIFY WITH DART P/N "D3531-041" USING WHITE MARKER ON INSIDE OF BRACKET ASSEMBLY, WHERE INDICATED

4) TRANSFER DRILL HOLES FROM D3531-1 BRACKET THROUGH D3531-3 BRACKET FRONT PLATE **BEFORE FINISHING** 

#### **PARTS LIST**

QTY.	P/N	DESCRIPTION
X	D3531-041	BRACKET ASSEMBLY
1	D3531-1	BRACKET
1	D3531-3	BRACKET FRONT PLATE
12	MS20470AD4-4	RIVET


#### COPYRIGHT © 2007 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

	- copace -								
W/O:		<del></del>	WO	RK ORDER CHANGI	ES	• 11			
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								,	
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No <b>DQ</b>	<b>A</b> :	_ Date: _	
	Res	olution:	Disposition	:	QA: N/C Clo	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC	<del></del>	Corrective Action Section		Verific	cation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		on C	Chief Eng	QC Inspector
						i			



DESIGN CB	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO, O	
CHECKED	APPROVED	DRAWING NO.	REV. A SHEET 2 OF 3
DATE <b>07.0</b>	06.19	BRACKET ASSEMBLY	SCALE 1:2



NOTES:
1) MATERIAL: ALUMINUM 6061-T6/T62 SHEET, 0.040 THICK PER QQ-A-250/11 OR AMS 4025 OR AMS 4027 (REF DART SPEC M6061T6S.040)
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1


- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
- 5) BREAK ALL SHARP CORNERS TO 0.010 MAX
- 6) PART IS SYMMETRIC ABOUT &


#### **COPYRIGHT © 2007 BY DART AEROSPACE LTD**

	. oopaot									
W/O:			W	ORK ORDER CHANGI	ES		•	•		
DATE	STEP	PRO	OCEDURE CH	ANGE	B	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·								
Part No	:	PAR #:	Fault Cate	egory:	NCR: Y	es N	lo <b>DQ</b>	A:	_ Date: _	
	R	esolution:	Disposition	on:	_ QA: N/	C Clos	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (N	CR)				
DATE	STEP	Description of NC		Corrective Action Section			Verific	cation	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		gn & late		ion C	Chief Eng	QC Inspector
								-		
<del> </del>										





DESIGN CB	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
CHECKED	APPROVED	D3531	REV. A SHEET 3 OF 3
DATE 07.0	06.19	BRACKET ASSEMBLY	SCALE 1:2





### D3531-3F FLAT PATTERN





## **D3531-3 BRACKET FRONT PLATE**

- NOTES:
  1) MATERIAL: ALUMINUM 6061-T6/T62 SHEET, 0.040 THICK PER QQ-A-250/11 OR AMS 4025 OR AMS 4027 (REF DART SPEC M6061T6S.040)
  2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
  3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

- 4) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
  5) BREAK ALL SHARP CORNERS TO 0.010 MAX
  6) PART IS SYMMETRIC ABOUT &

#### COPYRIGHT © 2007 BY DART AEROSPACE LTD

	•										<b>*</b> .	
W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			_								·	
			•							ı		
Part No:		PAR #:	Fault Category:			NCR: Y	es N	o <b>D</b> Q.	<b>A</b> :	_ Date: _	<u> </u>	
	Re	esolution:	n: Disposition:			_ QA: N/C Closed:				Date:		
NCR:		,	WORK OR	DER NON-	CONFORMAN	ICE (N	CR)			- · · ·		
DATE	STEP	Description of NC	Corrective Action Sec					Verification		Approval	Approval	
DAIL	SIEF	Section A	Initial Chief Eng		<b>Description</b> Chief Eng		Sign & Section				QC Inspector	
•						•						
			,	·			:	14.				
											·	
·												
									:			